

VEHICLE INSPECTION REPORT

SJ15UBR

Vauxhall Vivaro 2900 1.6CDTI 115PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 31/03/2015

Year 2015

Mileage 80,448 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN W0L3F7018FV628400

Body Style Panel Van MWB

MOT Due 17/12/2026

CAP Clean £3,250.00

CAP Average £2,600.00

CAP Below £1,825.00

Gearbox MANUAL

Gears 6

SIDE LOAD DOOR, ROOF RACK, E/MIRRORS.

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Radio/CD
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover of
Torn
Over 3mm



2: Carpets Front
Torn
Over 10mm



3: Bonnet
Chipped
Multiple Chips

4: Door osf
Dented
Over 30mm



5: Qtr Panel osr
Dented
With Paint Damage

6: Tailgate
Dented
With Paint Damage



7: Qtr Panel nsr
Dented
With Paint Damage

8: Door nsf
Dented
With Paint Damage

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK